

TSMD Campbell Field Activity Trip Report Week of June 7-11, 2021

Report Preparer: Todd Campbell, RPM, Region 7 SEMD/LMSE/MSRS

Manager: Cody McLarty, Chief, Region 7 SEMD/LMSE/MSRS

Note: For additional details, consult field logbook and corresponding email traffic, field activities as follows:

MONDAY 6/7- Conducted QA sampling at SCS work area 1i (Aggus) (Newton County) with Kim Burr in the morning. Afternoon checked on work by A&M on the HUBZone contract. They were loading out at MW34 (Oronogo-Duenweg; Jasper County). Two trucks were running without tarping their dirty material in the trucks so took photos and passed them along to Jon Huthsing the SS. Also went to Gypstack (Jasper County Repository for Oronogo-Duenweg RA work) to check on shaft and erosion damage. Sent Steve photo of erosional area on south side of cap. Checked on Short Creek sediment trap pilot project post large rain and found it nearly full of bedload material (Cherokee County SUPR Site; Cherokee County, KS OU5).

TUESDAY 6/8- Met Kim and the Field Techs at Hillbilly Pumping office (Oronogo-Duenweg; Jasper County). Placed orange plastic construction barrier/fencing around Wald's new mine in the morning. Later in the morning met with Mr. Fortner about his downed trees and leaning trees, drainage, septic system, and falling onto wire in an area on his neighbor's property where EQM had completed remediation (Oronogo-Duenweg; Jasper County). Took photos and passed information onto Steve Kemp so he could work on a restoration agreement. Afternoon, to Bronson, KS to look at area where oil had spilled to ground last May/June. Gathered information while on-site with James Johnson and Griff Hoffman then reported back up to RMs. See James Johnson's (EPA OSC) Trip Report to Heath Smith for more details.

TSMD TRIP REPORT PHOTOLOG



| | |
|---------------|---|
| DATE: | 06/7/2021 |
| TIME: | 1426 |
| DESCRIPTION: | Short Creek Pilot Study area – pilot test sediment trap full (IMG – 0892.jpg) |
| DIRECTION: | NW |
| PHOTOGRAPHER: | Campbell |



| | |
|---------------|---|
| DATE: | 06/08/2021 |
| TIME: | 1159 |
| DESCRIPTION: | Collapsed shaft at Wald/snowball mine with installed warning fencing (IMG 0893.jpg) |
| DIRECTION: | SE |
| PHOTOGRAPHER: | Campbell |

TSMD TRIP REPORT PHOTOLOG



| | |
|---------------|---|
| DATE: | 05/28/2021 |
| TIME: | 1222 |
| DESCRIPTION: | Leaning trees at Fortner Property (IMG 894.jpg) |
| DIRECTION: | NW |
| PHOTOGRAPHER: | Campbell |




| | |
|---------------|--|
| DATE: | 06/08/2021 |
| TIME: | 1222 |
| DESCRIPTION: | Stump of tree that fell during last storm on May 27, 2021 (IMG-0895.jpg) |
| DIRECTION: | WSW |
| PHOTOGRAPHER: | Campbell |

TSMD TRIP REPORT PHOTOLOG



| | |
|---------------|---|
| DATE: | 6/08/2021 |
| TIME: | 1222 |
| DESCRIPTION: | More leaning trees at Fortner Property (IMG 0896.jpg) |
| DIRECTION: | SSW |
| PHOTOGRAPHER: | Campbell |



| | |
|---------------|--|
| DATE: | 6/08/2021 |
| TIME: | 1223 |
| DESCRIPTION: | Top of tree near home that is leaning along with dead limbs (IMG 0897.jpg) |
| DIRECTION: | S and up |
| PHOTOGRAPHER: | Campbell |

TSMD TRIP REPORT PHOTOLOG



| | |
|---------------|---|
| DATE: | 6/08/2021 |
| TIME: | 1223 |
| DESCRIPTION: | Leaning tree at Fortner Property (IMG 0898.jpg) |
| DIRECTION: | WSW |
| PHOTOGRAPHER: | Campbell |

